YTD Safety/Human Performance

July 9, 2007

<u>Safety</u>

- Days Since Last OSHA Recordable 117 Previous Best 510
- Days Since Last Injury 12 Site Goal 0 OSHA Recordables
- Number of Open Safety Action Items None

Human Performance

• Days Since Last Error - 113



GREAT CATCH - While performing Emergency Feedwater (EFW) Heat Trace scanner replacement **Steve Hutzleman** and **Mack Rodrigue** discovered the field wiring did not match the controlled drawing. There was an extra wire terminated at one termination point which belonged to HT ITC0001-12 heat trace <u>controller</u>. Determination of the wire would cause a loss of the heater while the recorder neutral is determinated, potentially affecting the EFW pump AB. W3 Spotlight Be HERE...Now! Focus on.... What's the worst thing that can happen?



	<u>Yesterday</u>	<u>2007</u>
Near Miss:	0	9
First Aid:	0	3
OSHA Recordable	: 0	1
Lost Time:	0	0
HU Errors:	0	2
HU Events:	0	1





Waterford 3

SAFETY STATUS REPORT		KEY CONTACTS	Name	Phone/Ext/Pager	
Last 24 hrs * YTD D	ays Since Last	Shift Manager (Day)	Jarrell, J.	3104 / 225-951-010	4
First Aid Cases 0 3	12	Shift Manager (Night)		3104 / 504-471-910	
OSHA Recordable 0 1	117	Duty Manager	Peters, Bob	504-458-8369 / 313	
Days Away From Work 0 0	3705	Work Week Manager	Glueck, J.	3888 / 504-268-356	
Last DAFW - 5/17/1997		Engineering Duty Manager	Putnam, Rex	/ 3877 / 504-268-40	
		ERO Team	Orange	, 20, , , 20, 200 10	
EVENT FREE CLOCK STATUS			8-		
Station Resets: 1 Last: 1/10/2007				Data	D
Last Event: Incorrect wire termination resulted i	in CVAS Train A	STATION CONCERNS		Date	<u>Resp.</u>
Inoperability and 7 day SD LCO en	try	None			
SUCCESS DAYS					
Previous Best: Current:	Last Occurrence:				
RADIOLOGICAL EXPOSURE (PERSON	I-REM)	EMERGENT WORK		Date	Resp.
	DAL (Rem)	None			
Week:	0.067				
Cumulative: 3.1 104%	2.968				
CURRENT PLANT STATUS		OPERATIONS ISSUES		Date	<u>Resp.</u>
Rx Power	100 %	EDG A2 Air Start Compressor C	Control Power Fuse Blown (new)	07/09/07	Raines, D
MW Gross 1	212 MW	1	· · · ·		
		Adjust oil levels in Eccential AR		07/09/07	Pellegrin R
	161 MW	Adjust oil levels in Essential AB		07/09/07	Pellegrin, B
MW Net 1 Days of Continuous Operation	194 Days	PSL-203 failed stroke test. Limit	t Switch Adjusted Once; Needs	07/09/07 07/10/07	Pellegrin, B Raines, D
MW Net 1 Days of Continuous Operation Total RCS Leakage (24 hr average)	194 Days 0.17 GPM	PSL-203 failed stroke test. Limi Second Adjustment WO 11509	t Switch Adjusted Once; Needs 7	07/10/07	Raines, D
MW Net 1 Days of Continuous Operation 1 Total RCS Leakage (24 hr average) 0 Unidentified Leakage (24 hr average) 0	194 Days 0.17 GPM 0.15 GPM	PSL-203 failed stroke test. Limi Second Adjustment WO 11509 LWM-141 has valve body leak of	t Switch Adjusted Once; Needs	07/10/07	0
MW Net 1 Days of Continuous Operation 1 Total RCS Leakage (24 hr average) 0 Unidentified Leakage (24 hr average) 0 Heat Sink Temperature 0	194 Days 0.17 GPM 0.15 GPM 84 Deg. F	PSL-203 failed stroke test. Limi Second Adjustment WO 11509 LWM-141 has valve body leak of 101904 (new)	t Switch Adjusted Once; Needs 7 causing RAB oil sump level to rise WI	07/10/07 R 07/11/07	Raines, D Raines, D
MW Net 1 Days of Continuous Operation 1 Total RCS Leakage (24 hr average) 0 Unidentified Leakage (24 hr average) 0 Heat Sink Temperature 4 1	194 Days 0.17 GPM 0.15 GPM 84 Deg. F 8 SCFM	PSL-203 failed stroke test. Limi Second Adjustment WO 11509 LWM-141 has valve body leak of 101904 (new)	t Switch Adjusted Once; Needs 7	07/10/07	Raines, D
MW Net 1 Days of Continuous Operation 1 Total RCS Leakage (24 hr average) 0 Unidentified Leakage (24 hr average) 0 Heat Sink Temperature 1 Air In-Leakage 1 RCS Boron 1	 194 Days 0.17 GPM 0.15 GPM 84 Deg. F 8 SCFM 1069 PPM 	PSL-203 failed stroke test. Limi Second Adjustment WO 11509 LWM-141 has valve body leak of 101904 (new) CW Rad Monitor sample pump in (new)	t Switch Adjusted Once; Needs 7 causing RAB oil sump level to rise Wi motor fan is rubbing WR 101865	07/10/07 R 07/11/07 07/11/07	Raines, D Raines, D Raines, D
MW Net 1 Days of Continuous Operation 1 Total RCS Leakage (24 hr average) 0 Unidentified Leakage (24 hr average) 0 Heat Sink Temperature 4 Air In-Leakage 2 RCS Boron 1	194 Days 0.17 GPM 0.15 GPM 84 Deg. F 8 SCFM	PSL-203 failed stroke test. Limi Second Adjustment WO 11509 LWM-141 has valve body leak of 101904 (new) CW Rad Monitor sample pump in (new)	t Switch Adjusted Once; Needs 7 causing RAB oil sump level to rise WI	07/10/07 R 07/11/07	Raines, D Raines, D
MW Net 1 Days of Continuous Operation 1 Total RCS Leakage (24 hr average) 0 Unidentified Leakage (24 hr average) 0 Heat Sink Temperature 1 Air In-Leakage 1 RCS Boron 1 Gen. Hydrogen Use 1	194 Days 0.17 GPM 0.15 GPM 84 Deg. F 8 SCFM 1069 PPM 290 SCFD	PSL-203 failed stroke test. Limi Second Adjustment WO 11509 LWM-141 has valve body leak of 101904 (new) CW Rad Monitor sample pump if (new) PMC AO/RO controller for Mux 114874	t Switch Adjusted Once; Needs 7 causing RAB oil sump level to rise Wi motor fan is rubbing WR 101865	07/10/07 R 07/11/07 07/11/07 07/15/07	Raines, D Raines, D Raines, D
MW Net 1 Days of Continuous Operation 1 Total RCS Leakage (24 hr average) 0 Unidentified Leakage (24 hr average) 0 Heat Sink Temperature 1 1 Air In-Leakage 1 1 RCS Boron 1 1 Gen. Hydrogen Use 1 1 CHEMISTRY: Daily CPI: 1.00 7 Day C	194 Days 0.17 GPM 0.15 GPM 84 Deg. F 8 SCFM 1069 PPM 290 SCFD	PSL-203 failed stroke test. Limi Second Adjustment WO 11509 LWM-141 has valve body leak of 101904 (new) CW Rad Monitor sample pump if (new) PMC AO/RO controller for Mux 114874	t Switch Adjusted Once; Needs 7 causing RAB oil sump level to rise Wi motor fan is rubbing WR 101865 c RAB4602 cycles periodically WO Cooldown Cycle Timing, WO 104502	07/10/07 R 07/11/07 07/11/07 07/15/07	Raines, D Raines, D Raines, D Raines, D
MW Net 1 Days of Continuous Operation 1 Total RCS Leakage (24 hr average) 0 Unidentified Leakage (24 hr average) 0 Heat Sink Temperature 1 1 Air In-Leakage 1 1 RCS Boron 1 1 Gen. Hydrogen Use 1 1 CHEMISTRY: Daily CPI: 1.00 7 Day C	194 Days 0.17 GPM 0.15 GPM 84 Deg. F 8 SCFM 1069 PPM 290 SCFD	PSL-203 failed stroke test. Limi Second Adjustment WO 11509 LWM-141 has valve body leak of 101904 (new) CW Rad Monitor sample pump f (new) PMC AO/RO controller for Mux 114874 Investigate EDG B Inconsistent of	t Switch Adjusted Once; Needs 7 causing RAB oil sump level to rise Wi motor fan is rubbing WR 101865 c RAB4602 cycles periodically WO Cooldown Cycle Timing, WO 104502	07/10/07 R 07/11/07 07/11/07 07/15/07 3 07/16/07	Raines, D Raines, D Raines, D Raines, D Marble, D
MW Net 1 Days of Continuous Operation Total RCS Leakage (24 hr average) 0 Unidentified Leakage (24 hr average) 0 Heat Sink Temperature Air In-Leakage RCS Boron 1 Gen. Hydrogen Use CHEMISTRY: Daily CPI: 1.00 7 Day C Item/Limit Na+/0.8 CI-/5 Sulfat	194 Days 0.17 GPM 0.15 GPM 84 Deg. F 8 SCFM 1069 PPM 290 SCFD	PSL-203 failed stroke test. Limi Second Adjustment WO 11509 LWM-141 has valve body leak of 101904 (new) CW Rad Monitor sample pump f (new) PMC AO/RO controller for Mux 114874 Investigate EDG B Inconsistent of	t Switch Adjusted Once; Needs 7 causing RAB oil sump level to rise Wi motor fan is rubbing WR 101865 c RAB4602 cycles periodically WO Cooldown Cycle Timing, WO 104502	07/10/07 R 07/11/07 07/11/07 07/15/07 3 07/16/07	Raines, D Raines, D Raines, D Raines, D Marble, D
MW Net 1 Days of Continuous Operation 1 Total RCS Leakage (24 hr average) 0 Unidentified Leakage (24 hr average) 0 Heat Sink Temperature 1 1 Air In-Leakage 1 1 RCS Boron 1 1 Gen. Hydrogen Use 7 1 CHEMISTRY: Daily CPI: 1.00 Item/Limit Na+/0.8 CI-/5 SUffar 0.24 0.58 0.5	194 Days 0.17 GPM 0.15 GPM 84 Deg. F 8 SCFM 1069 PPM 290 SCFD CPI: 1.00 Goal: 1.00 te/1.7 Iron/5 Copper/0.2	PSL-203 failed stroke test. Limi Second Adjustment WO 11509 LWM-141 has valve body leak of 101904 (new) CW Rad Monitor sample pump f (new) PMC AO/RO controller for Mux 114874 Investigate EDG B Inconsistent of	t Switch Adjusted Once; Needs 7 causing RAB oil sump level to rise Wi motor fan is rubbing WR 101865 c RAB4602 cycles periodically WO Cooldown Cycle Timing, WO 104502	07/10/07 R 07/11/07 07/11/07 07/15/07 3 07/16/07	Raines, D Raines, D Raines, D Raines, D Marble, D



Waterford 3

ODMIs IN EFFECT (AP-12.11/EN-LI-111)	<u>Resp.</u>	RISK ASSESSMENT COLOR	RISK COMPONENT	
Primary to Secondary Leakage	Dolese, G.	Green		
RCP 2A Shaft Vibration	Taylor, J			
Startup Transformer B Positive Acetylene	Brauner, E			
Pressurizer Dissimilar Metal Welds	Taylor, J			
AC Air Side Seal Oil Pump Failure	H Leblanc			
MFIV A Control Air Leakage	Ket Van Le			
WF3 Cycle 15 Fuel Failure	Bruce Proctor			
SCHEDULED DOWNPOWER AND IPTEs (Nex	<u>at 30 Days)</u>	PROTECTED EQUIPMENT		
None		Train A		
		LCO/AOT'S <72 HRS AND RISK	ACTIVITIES	Resp.
		None	ACHVIIES	
		L		
		HOMELAND SECURITY: Y	ellow - Elevated	

				Monday	, July 09, 2	2007				
		Wate	rforc	-	ation		t Stat	tus		
					BOARD DEFICIE					
EQUIPM ENT		WR/WO	ENTRY	PROBLEM			OWNER	FINISH	COMMENTS	
			DATE					DATE		
CP-8 Wet T Annunciato	ower BBasin Level L or,N0301	WR 100998	6/20/2007					7/11/2007	PAC Loop CI	necked
urbine Ro Marm	tor Vibration High	WO 103829	6/27/2007	Main Turbine bearing 4Y vibration Ta spiking causing multiple alarms.		Talazac, C	7/12/2007	Temp Mod E	C to lift lead	
EDG A 200 S Lamp on C	Second Load Block P-1	WR 101681	7/2/2007	200 Secon not Illumin	d Load Block I ating	Lamp is	Raines, D	7/24/2007		
				UNIT HOUS	SEKEEPING REP	PORT				
	TION / EQUIPMENT				BLEM DESCRIPT	TION			OWNER	ECD
oor 161, R /ing Area	AB -4 Airlock to RB	Corridor La	ampsNeed	Replacemer	nt.				Moore, T	7/9/2007
GB +40 So	uth Side Condenser	Several Lar	Several Lamps South of Condenser A Need Replacement (new)					Moore, T	7/18/2007	
AB +21 Q I	Deck	Clean Q De	Clean Q Deck Floor (new)					Linder, M	7/11/2007	
					STRIAL SAFET					
LOCA	TION / EQUIPMENT			PROB	BLEM DESCRIPT	TION			OWNER	ECD

Duty Plant Manager **Bob Peters** – Ext. 3135

Duty Engineering Manager **Rex Putnam**– Ext. 3877

Protected Train $\underline{\mathbf{A}}$

Waterford 3 Work Week Calendar Work Week **11-43** Train Week **B1 Duty ERO Team – Orange**

WWM – **J. Glueck** Ext. 3888 Pager – 268-3563

WMC – Ext. 3411

EM – 9, OT – 20

Monday, 07/09/07	Tues., 07/10/07	Wed., 07/11/07	Thurs., 07/12/07	Friday, 07/13/07	Sat., 07/14/07	Sun., 07/15/07
	T-10 & T-2 Review	T-6 Review	T+1 & T-15 Review			
Days	Days	Days	Days	Days	Days	Days
NE-004-002, Radial Peaking Factor NE-004-008, Reactivity Balance DCT Fan 5B Motor Maint. Polisher Vessel 'F' Maint. (2 Days) Essential Chiller 'AB' Oil Level Adjustment, 72 hour S/D LCO & Cascading during retest only	Site Safety Meeting, 7 & 11 am SA 'C' Outage OP-903-121, Misc. SI Valves IST Hydrogen Analyzer B cal <i>CS Riser Pump 'B' Seal</i> (2 days), 7 Day S/D LCO during Retest only, MELT	Site Safety Meeting, 7 am Error Free Site Cookout CPC Chl 'B' Functional CPC Chl 'D' Functional 'B' Essential Chiller Cycle Timer Modification, 4 hour duration, 72 hour S/D LCO & Cascading during retest only	All Hands Meetings, 8 & 10 ENI ChI 'C' Functional DCT 'B' Sump Mtr #2 Lube RAB Normal Ventilation Hi Perf. Filter Replacement Prop Htr #2 Bkr Latch adjuster replacement	OP-903-026, Verify ECCS Train 'B' Line- Up/Full of Water OP-903-050, ACC 'B' Operability, 72 hour S/D LCO & Cascading, 3 hr duration Verify WCT & DCT Fans Operate PMC Failover, Implementation of SGLPM PMC software	OP-904-004, Mn Gen H2 Leakrate OP-904-004 Mn Turb Functional OP-903-107, PPS ChI 'B' Functional Control Room Carpet Replacement	OP-903-107, PPS Chl 'B' Functional, RISK OP-903-076, FHB Train 'B' Operability OP-903-052, CVAS Train 'B' Operability
Nights	Nights	Nights	Nights	Nights	Nights	Nights
RCS Leak Rate OP-903-120, HRA Train 'B' IST VIv Test OP-903-120, BM IST VIv Test OP-903-120, GWM IST VIv Test	RCS Leak Rate OP-903-043, SBV 'B' Operability and VIv Test	RCS Leak Rate MS IP301B Cal, 48 hr pwr reduction TRM LCO, 6 hr duration OP-903-037, CCS Fans OP-903-063, CHW 'B' Operability OP-903-050, CC 'B' Disch Chk VIv Test	RCS Leak Rate	RCS Leak Rate	RCS Leak Rate OP-903-013, SM Chl Check	RCS Leak Rate COLSS Power Chl Check Containment Sump Flow Loop Calibration
Safety Index	Safety Index	Safety Index	Safety Index	Safety Index	Safety Index	Safety Index
10.0 Green	10.0 Green	10.0 Green	10.0 Green	10.0 Green	10.0 Green	8.8 Yellow

Sponsors (*1) Kimberly Cook (Control Room) - (*2) Greg Hawkins (MELT) - (*3) Bryan Pellegrin (Safety Monitor)

Chemistry Department

Chemistry Performance Indicator				
Target	Goal	Current	YTD	7 Day
1.00	1.00	1.00	1.00	1.00

Fuel Reliability					
RCS Xe-133	Limit	Current	Trend	# of Failures	
Activity (uCi/cc)	N/A	9.43E-03	Stable	1	
RCS Dose Equivilant lodine	Limit	Current	Trend		
Activity (uci/gm):	<u><</u> 1.0	1.79E-03	Stable		
Fuel Reliability	Limit	Current	3 Mth Avg	YTD	
Index:	< 5.00 E-4	2.42E-05	1.94E-05	1.63E-05	

S	CW	
Stator Out DO2	: 0.0	Stable
Stator Out Cond	: 1.299	Stable
Demin Out Cond	<mark>:</mark> 0.166	Stable

	Secondary						
S/G's	Target	Limit	S/G #1	S/G #2			
Sodium (ppb):	<u><</u> 0.8	<u><</u> 5.0	0.24	0.28			
Chloride (ppb):	<u><</u> 5.0	<u><</u> 10	0.58	0.72			
Sulfate (ppb):	<u><</u> 1.7	<u><</u> 10	0.26	0.42			
Cation Cond:	-	<u><</u> 1.0	0.20	0.21			
Molar Ratio:	0.65	0.55 - 0.80	0.62	0.58			
Blowdown:	-	-	73	78			
CONDENSATE	Target	Limit	Current				
FW Iron (ppb):	< 5.0	<u><</u> 5.0	2.12				
FW Copper (ppb):	< 0.2	<u><</u> 0.2	0.002				
CD DO ₂ (ppb):	< 7.0	<u><</u> 10.0	2.51				
Off Gas (SCFM):	-	<u><</u> 13.0		8			

Primary to Secondary Leakage				
Current Leakrate (GPD):	1.2			
Normal Operations:	< 2 GPD			
Increased Monitoring:	> 2 GPD and < 5 GPD	1		
Action Level 1:	<u>></u> 5 GPD and < 15 GP	D		
Action Level 2:	<u>> 5 GPD and > 7.5 GP</u>	PD/HR for > 30 M IN		
Action Level 3:	<u>></u> 15 GPD			

LCO Requirement	
	S

Liquid and Gaseous Radioactive Waste					
S	Status as of:	6/5/2007			
Liquid Release Data	Goal	YTD	YTD Expected	2007 Expected	
Activity (m Ci):	131.1	133.8	118.2	176.0	
BWM Vol. (gal):	383,200	0	0	383,200	
LWM Vol. (gal):	500,250	277,029	191,400	585,879	
Gaseous Release Data	Goal	YTD	YTD Expected	2007 Expected	
Gas Activity (Ci):	4	0	0	4	

COMMENTS	
Leak rate based on gas isotopic method using AE PIG.	

LWM volume and activity elevated due to CCW drainings -- CR-WF3-2007-1150

Duty Plant Manager **Bob Peters** – Ext. 3135

Duty Engineering Manager **Rex Putnam**– Ext. 3877

Protected Train A

Waterford 3 Work Week Calendar Work Week **11-43** Train Week **B1 Duty ERO Team – <u>Orange</u>**

WWM – **J. Glueck** Ext. 3888 Pager – 268-3563


WMC – Ext. 3411

EM – 9, OT – 20

Monday, 07/09/07	Tues., 07/10/07	Wed., 07/11/07	Thurs., 07/12/07	Friday, 07/13/07	Sat., 07/14/07	Sun., 07/15/07
	T-10 & T-2 Review	T-6 Review	T+1 & T-15 Review			
Days	Days	Days	Days	Days	Days	Days
NE-004-002, Radial Peaking Factor NE-004-008, Reactivity Balance DCT Fan 5B Motor Maint. Polisher Vessel 'F' Maint. (2 Days) Essential Chiller 'AB' Oil Level Adjustment, 72 hour S/D LCO & Cascading during retest only	Site Safety Meeting, 7 & 11 am SA 'C' Outage OP-903-121, Misc. SI Valves IST Hydrogen Analyzer B cal <i>CS Riser Pump 'B' Seal</i> (2 days), 7 Day S/D LCO during Retest only, MELT	Site Safety Meeting, 7 am Error Free Site Cookout CPC Chl 'B' Functional CPC Chl 'D' Functional 'B' Essential Chiller Cycle Timer Modification, 4 hour duration, 72 hour S/D LCO & Cascading during retest only	All Hands Meetings, 8 & 10 ENI ChI 'C' Functional DCT 'B' Sump Mtr #2 Lube RAB Normal Ventilation Hi Perf. Filter Replacement Prop Htr #2 Bkr Latch adjuster replacement	OP-903-026, Verify ECCS Train 'B' Line- Up/Full of Water OP-903-050, ACC 'B' Operability, 72 hour S/D LCO & Cascading, 3 hr duration Verify WCT & DCT Fans Operate PMC Failover, Implementation of SGLPM PMC software	OP-904-004, Mn Gen H2 Leakrate OP-904-004 Mn Turb Functional OP-903-107, PPS Chl 'B' Functional Control Room Carpet Replacement	OP-903-107, PPS Chl 'B' Functional, RISK OP-903-076, FHB Train 'B' Operability OP-903-052, CVAS Train 'B' Operability
Nights	Nights	Nights	Nights	Nights	Nights	Nights
RCS Leak Rate OP-903-120, HRA Train 'B' IST VIv Test OP-903-120, BM IST VIv Test OP-903-120, GWM IST VIv Test	RCS Leak Rate OP-903-043, SBV 'B' Operability and VIv Test	RCS Leak Rate MS IP301B Cal, 48 hr pwr reduction TRM LCO, 6 hr duration OP-903-037, CCS Fans OP-903-063, CHW 'B' Operability OP-903-050, CC 'B' Disch Chk VIv Test	RCS Leak Rate	RCS Leak Rate	RCS Leak Rate OP-903-013, SM Chl Check	RCS Leak Rate COLSS Power Chl Check Containment Sump Flow Loop Calibration
Safety Index	Safety Index	Safety Index	Safety Index	Safety Index	Safety Index	Safety Index
10.0 Green	10.0 Green	10.0 Green	10.0 Green	10.0 Green	10.0 Green	8.8 Yellow

Sponsors (*1) Kimberly Cook (Control Room) - (*2) Greg Hawkins (MELT) - (*3) Bryan Pellegrin (Safety Monitor)

Operating Experience Industry Summary



- Point Beach (PWR W) OE24868
 - High Radiation Area and Locked High Radiation Area Barrier Violations
- Lessons Learned
 - All radiation workers are personally responsible for ensuring they are properly logged in on the correct radiation work permit (RWP) and meet all the necessary requirements prior to entry into any controlled access area (CAA).

Forced Outage Readiness

Other Potential Materialis Other Researce Participation Materialis Potential Materi									
00103499-01 XXXMECHANICAL MECFUN MECH RCP SEAL SPARE, REBUILD SEAL Bruce 16-Oct-07 2nd Spare Seal 18-Apr-07 09:00 09:00 17:00 100 100 100 100 100 Hot Shutdown Required Packages – Ready Heady 100 100 100 100 100 100	Activity ID	UNID	CO EQUIPMENT-TY	E LEAD-DIS	Activity Name	Action Owner	Expected Finish	Notes to Resources	Added to FOL
Hot Shutdown Required Packages – Ready	Potential Materials			1			16-Oct-07	•	18-Apr-07
	00103499-01	XXXMECHANICAL	MECFU	MECH	RCP SEAL SPARE, REBUILD SEAL			2nd Spare Seal	
		1					<u>\</u>		
Cold Shutdown Required Packages - Ready	Hot Shutdown Required Packages – Ready								
	Cold S	hutdown	Requi	red	Packages - Ready	/			

Monday, July 09, 2007 Current Protected Train - A Risk Color – Green

Personnel, Nuclear, and Radiological Safety Equipment Priorities:

- Essential Chiller 'AB' Oil Level Adjustment
- Polisher Vessel 'F' Maintenance
- Dry Cooling Tower Fan 5B Motor Maint.